

V.

23 MAY 1945

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

EL'S NAME "ST. ANNE" REPORT Lon. No. 112776

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The vessel's class is subject to Annual Survey, this being duly recorded in the Register Book.

Action has been deferred for Annual Survey due 8.44.

The LONDON Surveyors report this barge placed on blocks, bottom coated, and Annual Survey carried out, the broken concrete in way of forward corners of hatch coaming (p.s.f) and at forward end of shell (p & s) cut out and new concrete laid.

IT IS SUBMITTED the vessel is worthy to remain as classed with record of docking and Annual Survey 4.45.

4.45 Lon.

A.S. 4.45

JJ CAM  
17/5/45

CARGO BATTENS, HATCH COVERS AND CEILING NOT FITTED.



© 2020

Lloyd's Register  
Foundation

007626-007638-0015