

s/s "Elfsborg".

To complete the survey for the classification of this vessel's machinery, the cylinders, pistons, slide valves, pumps, condenser & bilge suction's require to be examined.

Del. 2.15

JWR

15/1/20

JFR

© 2020

Lloyd's Register
Foundation

007626-007638-0250