

Westpolder

Rot. 18709

It is submitted the Surveyors be requested
to state the fire grate area for each Boiler
whether the Engines & Boilers were in use
before being fitted in this vessel.

Lt. Rot.
23/1/29

J. L.

23/1/29

007639 - 007646 - 0215

Is the arrangement of Valves and their connections such as to prevent the possibility of water passing from the sea or from water tanks into the cargo hold?