

Received by Chief Ship Surveyor 28.10.18

Received from Chief Ship Surveyor _____

VESSEL'S NAME Success Himalaya Maru Rpt. Mag No. 1198

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 87.5

Depth "d" 18

Framing: Table No. 3

Description Bulk angle & several frames as approved

Longitudinal No. 33800

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.6}{1}$

Bridge Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \star 100A-1 (Steel) as recommended.

2 Dxs (Steel)

Cell D.B. 35' 1075L. F.P.T. 130L A.P.T. 87L

FK. 6BH. Cen. A+CP. P39' B12' F40'

M



© 2020 ¹⁰⁻¹⁸

Lloyd's Register Foundation

007679-007679-0149