

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

ESSEL'S NAME *S.S. "HOKUROKU MARU"* Rpt. *Nag* No. *1757*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

*1st Long*  
Transverse No. *18134*

Depth "d" *19.42*

Framing: Table No. Description *Bulb angle frames as approved.*

Longitudinal No. *45056*

Proportions Length = *10.92*  
Depth

Deck Sheerstrake *as approved*

*Revised Rules.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *✱ 100A1 (Steel)* with freeboard," as recommended. *fitted for carrying oil (11.30) FP above 150° F in Deep Tanks* The Summer freeboard of *5 ft 4 in* from centre of disc to top of statutory deck line at — deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

*3 D<sup>ks</sup> (Stl)*

*Cell DB 373'1295t, Tanks in way of tunnels 978t, MTs 36'1185t, FPT 96t, APT 89t.*

*FK, 8BH (Coll BH to weather D<sup>k</sup> 7BH to 2<sup>nd</sup> D<sup>k</sup>), pt Cem, Lloyd's A & CP*

*F 40'*

