



S. NO 93.

SKETCHES SHOWING POSITIONS OF GROOVES ON SHAFT BRACKET  
IN WHICH A FEW SURFACE CRACKS OF  $\frac{1}{2}$ " TO  $\frac{3}{4}$ " LONG WERE OBSERVED  
LOOKING FORWARD





CHAIN LINES SHOW EDGES OF O.S. PLATES

SECTION AT M.N.



PLAN



Registered Foundation

007679-007673-0253

007679-007673-0254