

For the information of Surveyors and the Committee only.

Received at

Office,

19

Lloyd's Register of Shipping.

(Report on Machinery, No. 992 Port)

No. 884 ENGINE FORGINGS ~~OR CASTINGS~~

I have to report that the ~~Iron or Steel Forgings or Castings~~, as herein described, manufactured by Todd DDT Construction Co of Tacoma W. for the Engines No. 33 being constructed by Sam E of Sam E for the Ship No. 33 being built by Todd DDT Const Co of Tacoma W. have been inspected by me as set forth below, and found to be, so far as can be seen,

Sam E Free from Defect

Forgings or Castings

Lloyd's

No.

Subsea Link Bearings

W.P. Cullings / ch

Seattle W. Link Bearings Co.

~~CRANK SHAFT.~~

~~STRAIGHT SHAFTING:~~

~~THRUST SHAFT~~

~~INTERMEDIATE SHAFTS.~~

~~PROPELLER SHAFT.~~

*Stat of
Inspected
as Rept.
Rough*

Standard Pieces.

64920

62100

Test—

28.0

33.0

on per cent

180

180°

ending Test—

3-1-20

3-1-20

before fracture

When Inspected

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—


Lloyd's
No. 885
3-1-20
W.P.C

Lloyd's
No. 884
3-1-20
W.P.C

(if any chargeable)

To be paid at

of iron, state whether scrap or puddled iron. If of steel, state whether made on the Open Hearth process



© 2020

Lloyd's Register Foundation

007714-007721-0359

007714-007721-0360