

1

Scania"MAIA"Sent to Chief Surveyors 11. 8. 17

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "DANE BROG" Report Chicago No. 12**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey 1st Entry When due

This vessel is without cargo battens. She has been examined in dry dock & some damage sustained during launching repaired.


✠ 100 A.I. (Steel)

1 DK (steel)

Cell DB 220' S28 E . FRT. 64 T . APT 44 T.

FK 4 B.H. Cem. Arch. . P 25' B 64' F 26'

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.



a.i.
13.8.17



© 2020

Lloyd's Register
Foundation

007722-007730-0252