

12(b).

FREEBOARD VERIFICATION FORM FOR STEAMERS CARRYING TIMBER DECK CARGOES.

When received in London Office _____

Ship's Name Tallin
Signal Letters E.S.R.L. No. in Reg. Book 31305-
Gross Tonnage 2218
Date of Verification _____
Name of Owners _____

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

NARY CARGO AND PASSENGER SHIPS.
OR

Freeboard amidships from top of deck line, <u>wood</u> /steel <u>upper</u> deck.	From centre of disc.
Tropical Fresh Water <u>731</u> ft. <u>n/a</u> ins.	<u>190</u> ins. above
Fresh Water <u>807</u> ft. <u>"</u> ins.	<u>114</u> ins. above
Tropical <u>845</u> ft. <u>"</u> ins.	<u>76</u> ins. above
Summer <u>921</u> ft. <u>"</u> ins.	
Winter <u>997</u> ft. <u>"</u> ins.	<u>76</u> ins. below
Winter North Atlantic <u>1048</u> ft. <u>"</u> ins.	<u>127</u> ins. below

3 CARRYING TIMBER DECK CARGOES.

Freeboard amidships from top of deck line, <u>wood</u> /steel <u>upper</u> deck.	From centre of disc.
Tropical Fresh Water Timber <u>381</u> ft. <u>n/a</u> ins.	<u>540</u> ins. above
Fresh Water Timber <u>502</u> ft. <u>"</u> ins.	<u>419</u> ins. above
Tropical Timber <u>502</u> ft. <u>"</u> ins.	<u>419</u> ins. above
Summer Timber <u>622</u> ft. <u>"</u> ins.	<u>299</u> ins. above
Winter Timber <u>781</u> ft. <u>"</u> ins.	<u>140</u> ins. { above
Winter North Atlantic Timber <u>1086</u> ft. <u>"</u> ins.	<u>165</u> ins. below

Maximum Summer Draught corresponding to the freeboard assigned as shown on Builders' Displacement Scales:—

Surveyor.

(To be filled up in London Office.)

Minutes of Committee's Minute _____

Particulars for Record in Register Book. { Moulded Depth ft. ins.
Freeboard ft. ins.
Corresponding Draught ft. ins.

Freeboards compared and found correct by _____

Date _____

Form for Certificate _____

Certificate written _____

10 JUL 1937

Noted for posting _____

12.30.