

Dear Mr. Fowling:-

2:00, 12/19.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel BARGE NAVEGADORA N° 100 Report N.Y.R. No. 18478

For the CHIEF SHIP SURVEYOR ASTUTE ENGINEER, CENTRAL

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Excerpt from Sub-Committee's Report, 34/5/92.)

Nature of Survey _____

When due _____

A - (steel) Barge for being towed. "For Service in the Panuco River."
Carrying Petroleum in bulk.

1 Dk (steel).

FK. 3BH. pt.cem.

17/8/20

This concluded the deck stringer angle is as approved & that the diameters of spacing plates in frames are as required, but the Surveyors should be requested to state if this is so.

[Signature]

AES.

17.6.20
16.7.20

007770-007782-0239

12.5
12.7