

ANNUAL SURVEYS.

BOX CASE

4090

No. 334 Survey held at London Date, first Survey 10th Oct^r Last Survey 14th Oct^r 1881
 No. in on the Iron Bk. "Alastor." Master T. Glazebrook
 Reg. Book. 334 Net 824 Built at Sunderland When built 1875 10th Month.
 Tonnage { Gross 874 By whom built Mounsey & Foster Owners R. A. Penney
 Under Dk. 200 Port belonging to Shoreham Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock In the Commercial Dry Dock
 (State Name of Dock.)

Last Survey, No. 28015 Port of Iron

Classed

100 A-1.

Present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Rivets <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>5^o</u>	Breasthooks and Stemson <u>5^o</u>		Pumps <u>5^o</u>
Comings <u>5^o</u>	Transoms, Pointers, and Crutches <u>5^o</u>		Boats <u>5^o</u>
Upper Deck Beams & Fastenings <u>5^o</u>	Timbers of the Frame at the Openings <u>5^o</u>		Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>5^o</u>	Ditto ditto at other places <u>5^o</u>		Condition, how ascertained <u>from the deck</u>
Planksheers <u>5^o</u>	Keelsons <u>5^o</u>		Sails <u>good</u>
Sheerstrakes <u>5^o</u>	Clamps and Shelves <u>5^o</u>		Anchors, No. of <u>3 B. 1 P. 2 K.</u>
Topsides <u>5^o</u>	Ceiling <u>5^o</u>		Cables <u>complete</u>
Wales <u>5^o</u>	Rudder <u>5^o</u>		Hawsers and Warps <u>sufficient</u>
Plating <u>5^o</u>	Copper on Y.M. <u>When put on</u>		Standing and Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>5^o</u>	Caulking of <u>good</u>		
Engine Room Skylights <u>Coal Bunkers, Openings, Lids, &c.</u>	Bottom, Deck, & Waterways <u>good</u>	Scuppers <u>good</u>	Cargo and Main Hatchways <u>good</u>
			Hatches <u>good</u>

(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.

The bottom has been examined and coated; the rudder pintles repushed.
 Vessel surveyed with ballast and dunnage in the hold.
 She appears to be in good and efficient condition and eligible to remain as classed.

Committee's Minute Friday, October, 21st 1881.

Character assigned 100 A-1

J. A. Truscott
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage { Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of

Classed

Present Condition of the

Decks <u> </u>	Treenails <u> </u>	Windlass and Capstan <u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	Masts, Yards, &c. <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	Condition, how ascertained <u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	Sails <u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	Anchors, No. of <u> </u>
Topsides <u> </u>	Ceiling <u> </u>	Cables <u> </u>
Wales <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	Standing and Running Rigging <u> </u>
Engine Room Skylights <u> </u>	Caulking of <u> </u>	
Coal Bunkers, Openings, Lids, &c. <u> </u>	Bottom, Deck, & Waterways <u> </u>	
	Scuppers <u> </u>	Cargo and Main Hatchways <u> </u>
		Hatches <u> </u>


(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

007783-007793-0380