

REPORT of SURVEY for REPAIRS, &c.

No. 38719

No. in Reg. Book.

Survey held at

London

Date, first Survey

31st Oct.

Last Survey

26th Nov. 1879.

350 on the

Barge "Alastor"

Master

Glazebrook

TONNAGE under Tonnage Deck

800.

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Or. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

274.

Crew Space, as per Rule

Register Tonnage, cut on Beam

224.

Engine Room

Reg. Tons as St^rmer, cut on Bm.

Built at

Sunderland

When built

1875 - 10

Owners

R. H. Penny

Port belonging to

Shoreham

Residence

By whom built

Mcounsey

Destined Voyage

Wellington

If Surveyed Afloat or in Dry Dock

Princes Dry Dock & Afloat.

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

19388

Port

Shoreham

Classed

100 A.1.

8-77.

REPAIRS, OR EXAMINATION AS PER RULE

Part A. S. No 1.

Bottom examined, Rudder unhung and bushed, timbers and ceiling in hatches on each side lifted from the after part of main hatch to the fore hatch, also a short length under the after hatch, the Cement in good condition and firmly adhering to the Iron, bottom cleaned and coated with Paint and Tallow.

The remaining part of the Vessel could not be examined being covered with outward bound cargo.

Present Condition of the

Decks

Good

Waterways

— " —

Comings

— " —

Upper Deck Beams & Fastenings

— " —

Lower Deck Beams & Fastenings

— " —

Planksheers

— " —

Sheerstrakes

— " —

Topsides

— " —

Wales

— " —

Plate

(Bottom) and Counter

— " —

Engine Room Skylights

— " —

General Observations, Opinion as to Class, &c.

Timber

Rivets

Good

Breasthooks and Stems

— " —

Transoms, Pointers, and Crutches

— " —

Timbers of the Frame at the openings

— " —

Ditto

Ditto

at other places

— " —

Keelsons

— " —

Clamps and Shells

— " —

Ceiling

— " —

Rudder

— " —

Copper

Cement

When put on

1875

Caulking of

Bottom, Deck, & Waterways

Good

Windlass and Capstan

Good

Pumps

— " —

Boats

— " —

Masts, Yards, &c.

— " —

Condition, how ascertained

Deck & C.

Sails

Good

Anchors

No. of

313 - 15 - 28

Cables

Good

Hawsers and Warps

— " —

Standing & Running Rigging

— " —

Cargo and Main Hatchways

Good

Hatches Good

The Amount of Entry Fee ...

£

4

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

16/11/79 Special

£

2

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

Certificate (if required) ...

£

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

:

Committee's Minute

16th December,

1879.

Character assigned

100A

TRW

Thos Wm Blapell
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

007783-007793-0382

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

[4,600-33/978.]