

Fleming & Ferguson Ltd.

Yard No. 568
J. 1187

Surveyors.....

Received from Chief Surveyors.....

NAME..... CAVA..... Report..... Gls..... No. 64059

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

FIRST ENTRY..... When due.....

This is a sister vessel to the "ROMEO", "JUNIPER", etc.

GLOOA- "Stm Trawler"

"For Government Service"

FPT 16t DT of 15' 41t

FK, 7BH

pt 20p

F 27'

O.L. 164.5'

ESD

Note: for coating of floor - see sister vessels.

The Surveyors should be requested to give particulars of the coating of the bottom of the vessel if cement is not laid. If, as in some of the previous sister vessels, the bottom is coated partly of bitumastic and painted only clear of the tanks, this should be stated.


It might be pointed out that in the cases of sister vessels, "JUNIPER" etc., the particulars of tanks are as follows:-

F.W. tank fwd. 5.5' 10.4t

Trimming Tank 11.0' 17.35t

Reserve Feed 9.16' 28.40t

and information is desired as to whether the vessel now reported has a different arrangement of tanks.



© 2020

Lloyd's Register
Foundation

007806-07816-0188

23.7.41