

F.E.

Received by Chief Ship Surveyor 20.9.04

Received from Chief Ship Surveyor

L'S NAME *St. Louis S. S. "Anulua Castle"* Report *Bel.* No. *5790*

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>4 1/2"</i>	<i>Proportions</i>
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Channel with reverse frames as</i> (viz., ordinary, deep, zed, channel or bulb-angle). <i>per approved plans.</i>		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A 1 ("Steel") as recommended.

∇ 100 A 1 ("Steel")

3 BR (Stk - U Tank S)

M. B = Cell DB a 112' x E x B 99' f 191' 1327E DT f 43' 1115E FPT 846 APT 506

FK x BK 3" 8BH Cen. Plyd. AYCP P x B 315' F 70'



© 2020

C. H. J.
Lloyd's Register
Foundation

007817-007824-0220