

157

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office, \_\_\_\_\_ 19\_\_

# Lloyd's Register of British & Foreign Shipping.

(Report on Vessel No. 7286 Port Piastre)

## No. 1131 SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by Messrs. Withrow, Borgb., Eisenh. G.m.b.H. of Witkowitz for the Vessel No. 105, being built by Messrs. Cantiere Navale Triestino of Monfalcone have been inspected by me as set forth below and found to be, so far as can be seen, sound and free from defects

1 Sternframe in 2 parts

on Forgings or Castings.

Lloyd's

No. 1056

12.20

Vienna 21<sup>st</sup> December 1920

M. Hoch

	STERN FRAME.	RUDDER FRAME.	STEM.
Material	<u>annealed &amp; all steel</u>		
Made	<u>cast</u>		
Dimensions	<u>190x255 / 190x255</u>		
Condition on Inspection	<u>alm. finished</u>		
When Inspected	<u>23/4.20, 19/6.20, 7/12.20</u>		
CASTINGS.	<u>top part   bottom part</u>		
Conformity with Standard Test Pieces.			
Test—			
Strength per square inch	<u>29.1; 28.9; 28.5; 27.7</u>		
Elongation per cent. 3"	<u>31.6; 31.6; 30.3; 22.3</u>		
Bending Test—	<u>180° cold</u>		
Time before fracture	<u>satisfactory</u>		
Test—			
Distance from ground	<u>8 1/2", satisfactory</u>		
Ring Test—	<u>according to rules</u>		
Compliance according to Rules	<u>&amp; satisfactory</u>		
Found satisfactory			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(if any chargeable) £ \_\_\_\_\_

To be paid at Vienna

Iron, state whether scrap or puddled Iron. If of steel, state whether made on the Open Hearth process.

110-788700-188700

