

1m.6.44

1 E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME "BIGGAL"

REPORT Grk.  
G's.No. 23005  
69100  
69553

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Triple Expansion.

If Boilers fitted with forced draught

Yes

Tail Shaft. If fitted with a continuous liner


No

If fitted with an outside gland of }

approved type }

Yes

This vessel's machinery appears to have been built in accordance  
& Admiralty specification  
with the Rules and the approved plans, and it is submitted she is  
eligible to be classed LMC 4.45.



10.5.45.



© 2021

Lloyd's Register  
Foundation

007888-007894-0060