

1m.12.15.

F.E.

Received by Chief Ship Surveyor

22-9-17

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheela Venosta

Rpt.

1st

No. 30746

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

36-45

Depth "d"

11.75

Framing: Table No.

3-page 9

Description

Single angle as approved

Longitudinal No.

4920

Proportions

Length

= 10.32

Depth

~~Deck~~ Sheerstrake

-56 of an inch instead of 38 as reqd.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100 A-1 (Steel) Steam Trawler as recommended.

1. Dr.

BK 75 4 BH. Cam. Repaired. Q 74 F 21

Date of Repair 25.17.

M
22.9.17



© 2020

Lloyd's Register
Foundation

007919-007929-0006