

F.E.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

Ortona

'S NAME

Steel S.S. "ORTONA"

Rpt.

Apl.

No. 3197

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

transverse No. 38.25

Depth "d" 11.5

Diagram: Table No. 3 page 10.

Description Single angle and Bulb angle as approved.

Longitudinal No. 5737

Proportions Length = 11.5
Depth

Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100, A.1. (Steel) as recommended.

1 Dk. (Steel) Well Dk.

FPT 34t.

FK. 3 BH. Cem. Lloyd's A. & C.P. Q83', B9', F24'.

Date of build, 1.19.

Machinery aft.

M
10. 2. 19.



© 2021

Lloyd's Register Foundation