

50,17.

F.E.

Received by Chief Ship Surveyor *8/8/08*

Received from Chief Ship Surveyor

VESSEL'S NAME

*U.S.S. Kamo Maru*

Rpt.

*Nag*No. *613*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

## CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<del>50</del>	<i>Proportions</i>
Spar Sheerstrake . .		
Description of Framing:— <i>Deep framing, as approved.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

*The rudge anchor is 23 lbs less in weight than required by Table 22.*

*In other respects* This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ 100A1 (Steel)* as recommended.

*+ 100A1 (Steel)*

*2 Sts (Stt - U-Teak 5) + deep framing + sub frames lower deck (Stt) in two 143 holds.*  
*WB - Bul DBa 134 u 645 85 f 180 16095 F.P.T 1435 APT 48 DTA 26 5616*  
*F.K. 78.H Gen. Lloyd A + 60. P 61 B 176 F 54*



© 2020

Lloyd's Register Foundation

007981-007987-0069

Quarter 'tween Dks.,

Deck, Material and thickness