

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *ex. Steel S.S. "DALMAZIA"*

Rpt. *Mdb.* No. *10798.*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *8558* Depth "d" *24.4'*

Framing: Table No. *-* Description *Frames & Reversed Frames.*

Longitudinal No. *35216*

Proportions  $\frac{\text{Length}}{\text{Depth}} =$  *10.78*

*Shelter*  
Deck Sheerstrake as approved.

*This vessel is built with straight frames & a bevelled bilge.*

*The Downton Pump has been dispensed with for the present, but it is included the owners are agreeable to fit same when requested*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100 A.1 (steel) "Shelter Deck"* with the notation "Straight frames, bevelled bilge" with freeboard, "as recommended. The Summer freeboard of *10'-1"* from centre of disc to top of statutory deck line at *Shelter* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

*1 DK (steel) & Shelter DK (steel)*

*Cell DB 344' 1482t. DTA 23' 846t. FPT 97t. APT 119t.*

*FK. 5 BH to Shelter DK. 3 BH to upper DK. pt. com. Lloyd's ATCP. FAL on Shelter DK.*

The Certificate of Classification, to be endorsed *with Turret Deck* "Cargo battens not fitted," and the same notation to be printed in the Register Book.

*This included the thickness of the outside strips in E & F strakes areas required but the Surveyors should be requested to state if that is or*