

"HAMLET"

1m, 8, 21.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel Se Se SØBORG*

Rpt. *Hpl*

No. *16193*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

*1st Long.*  
Transverse No. *5972*

Depth "d" *18.5*

Framing: Table No.

Description *Bull angles as approved*

*2nd* Longitudinal No. *17124*

Proportions  $\frac{\text{Length}}{\text{Depth}} =$  *13.12 to upper Sk.*

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the *Revised* Rules and the approved plans, and it is submitted she is eligible to be classed


✱ 100A.1. (steel)

1 SK (steel)

cell D.B 240' 515t, A.P.T. 75t.

F.K, 4B.H, 1st cm, Lloyds ACP. P 23', B 83', F 28'.

The Surveyor should be requested ~~to~~ forward the letter from the owner agreeing to the vessel being built under the Revised Rules.



© 2020

Lloyd's Register Foundation

008061-008067-0105