

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S.S. "WAR HINDOO"

Report Grk.

No. 17562.

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

✱ 100 A-1. (steel) "Carrying Petroleum in Bulk"

1 DK (steel) 2 1/2 beams & Webframes. Longitudinal Framing

Cell DB 0E1364' 1325. f50' 645. FPT 275. APT 135.


FK. 15BH. ph. am. Lhyds ATCP. P50', B121', F33'

M *atS*
15-11-19

for Jark 22/1/1919

It is concluded the Forecastle deck beams are fitted to every frame as in sister vessel & as shown on plans, but the Surveyors should be requested to state if this is so.

The Surveyors should also state whether all the requirements, for the carriage of Petroleum in Bulk, have been complied with.



© 2021

Lloyd's Register
Foundation