COPY.

Lloyd's Register of Shipping.

Hamburg Report Nr. 24.124.

Port of Hamburg

28th June, 1939.

This is to Certify *that I have Surveyed the* Steel Sc. "G O N C A L O V E L H O", 1595 tons gross of Ponta Delgada in dry dock and afloat at this Port for damage stated to have been caused by fracture of intermediate propeller shaft on 8th June, 1939 xxxxxxxxxxxxxxxxxxxxxxxxxx *and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have* **Recommended** *that she be* eligible in my opinion to remain as classed ✠100 A1 Shelter deck with freeboard in the Societys Register Book, with fresh record of survey 6,39, xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx *being fit to carry* Dry and Perishable Cargoes. xxxxxxxxxxxxxxx xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx

R. B. Shepheard.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly ated, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances ever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any y in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its mittees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

—10m,8,37.

© 2021 Lloyd's Register Foundation

008087-008095-0262