

Hamburg Report Nr. 24 124

IF



Port of Hamburg

29th June, 1939.

Starb.

Surveyed the Boiler and Machinery of the Steel Sc.

G O N C A L O V E L H O " 1595 tons gross of Ponta Delgada,

float and in dry dock at Hamburg for damage, damage repairs
and Completion of B.S.

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

of **Recommended** that the record s of T.Sh (CL) new -6,39

and B.S. -5.39 .

be made in the Register Book in the case of this vessel.

Friedrich Hill

Engineer Surbeyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

-10m, 8, 37.

78.8.0