

1

Gonzalo Velho

Balboa

Sent to Chief Surveyors

19. 3. 13

now Balboa

Received from Chief Surveyors

VESSE'S NAME

M. S. Linnere

Report

LH

No.

16404

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Natio/ Survey

First Entry

When due

1- 100 A.1. (Stub) Shelter deck with plating  
 1 Dk (M) & Shelter dk (M)  
 W.R. Cell 5' 6" x 6' 6" x 6' 6" 395 t 3. P. 3. 29t. 4. P. 3. 29t.  
 F.R. 5' 6" x 6' 6" x 6' 6" Lays a & b. P.

M. W. W. 13  
 19. 3. 13

130880  
 10451  
 as  
 713



© 2021

Lloyd's Register  
Foundation