

Received by Chief Ship Surveyor

9/12/12

Received from Chief Ship Surveyor

VESSEL'S NAME

Hull 'EGIR'

Rpt.

Hul

No

25684

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

32.67

Depth "d"

7.96

Framing: Table No.

2 page 3

Description

Ordinary

Longitudinal No.

3887

Proportions

Length

Depth =

12.87

~~Deck~~ Sheerstrake

as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ 100 A1 (2nd) as unrounded

+ 100 A1. (2nd)

1st (2nd)

NB = DT 11' 406

FR Rep. Lloyd's 206P Q39 Fig 'Mch'y Aft'

4 B4



© 2021

Lloyd's Register
Foundation