

2m.11.35.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME "TEXACO 157". Report Gal. No. 3237

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

When due

FIRST ENTRY AND CLASSIFICATION.

A- "Barge to be towed"

"For Coastwise service in the Gulf of Mexico"

"Carrying petroleum in bulk".

IDK. "LONGITUDINAL FRAMING"

FK, 4 BH.

6,37 Gal.

S.S.Gal.No.3-6,37

O.L. 135'1"

NOTE. Extreme Breadth over belting: 35' 2 $\frac{1}{4}$ ".

PLATING to be DRILLED when  
vessel is 24 years old,  
or at next Special Survey  
thereafter.

*10.9.37*



© 2020

Lloyd's Register  
Foundation

008201-008210-0015

" " Angles

Poop Deck, Angle, E or F