

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl hwn Prop. Dredge " TELFORD Report Is No. 46139**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/93.)

Nature of Survey 1st Entry When due _____

✠ 100 A.I. (Steel) " Dredge"
 1 D* (Stl)
 M.T. 5' 20t.
 F.K, 9 B.H, Cem, Plyds A & CP.



© 2021

Lloyd's Register
 Foundation

008222-008230-0084

spacingg...

Middle Line Keelson, on Floors, Angles, _____

4½

3

.44

4½ x 3 x 39

Cabin Sole

amidships Angle Floor _____

5