

D.S. 399

F.E.

Im. 10.33.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Steel M.S. "THORHILD"

Rpt.

Got.

No. 10365

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

1st Long. No. 18606

Depth "d" -

2nd Long. No. 49806

Proportions = $\frac{L}{D}$ 12.77

Framing Bulb angle frames as approved

Sheerstrake ✓

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*100A1 Carrying Petroleum in bulk

1 Dk.

Cell. DB u E 70' 30lt DTf 33' 573t FPT 160t APT 311t

FK, 11 EH, pt Cem. Lloyd's A & CP

P 95' B37' F 71'

Machy. aft.

CONTINUOUS SURVEY



© 2021

Lloyd's Register
Foundation

008258-008267-0171

20.8.35

20

COMMUNICATIONS



© 2021
Lloyd's Register
Foundation