

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SSEL'S NAME Steel S Motor Tank Barge - HVITSK JAEH Rpt. Ret No. 12063

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 27 Depth "d" 8.2
Framing: Table No. - Description Single angle - as approved
Longitudinal No. 2673
Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{11}{1}$

~~Deck~~ Sheerstrake as approved

Part steel tested by Bureau Veritas Surveyors.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100-A-1. (Steel) Carrying petroleum in bulk
1 Dh (Steel)

FK, 813H, pt-Cem, Av CP. Q29' F16' Melay Off

[Signature]
7-12-21

It is concluded the Workmanship is good but the Surveyors should be requested to state if this is so.



64821

Lloyd's Register Foundation