

Ship's Name ..... RICHMOND HILL .....

Extract from Freeboard Verification of Marking Form  
received from the ... SUNDERLAND ..... Surveyors,  
dated ... 6th. November, 1940.

Moulded depth	38 ft.	3 ins.
Corresponding draught	28 ft.	2 $\frac{1}{2}$ ins.
Moulded depth as shown on draught sheet	38 ft.	3 ins.
Tropical freeboard	9 ft.	8 ins.
Summer           "	10 ft.	3 ins.
Winter           "	10 ft.	10 ins.
W.N.A.           "	- ft.	- ins.
Fresh Water allowance		7 $\frac{1}{4}$ ins.

Marked from ~~wood~~/steel upper deck.

Checked by ..... *Jm*

Date 13th December, 1940



© 2020

Lloyd's Register  
Foundation

008279 - 008287 - 0082