

5. 5. 20

6-MAY 1920

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Stl. S.S. "LIMA"-ex "WESTERWALD". Rpt. Lis. No. 1200

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."-Extract from Sub-Committee's Report, 24/5/22.)

urvey

This vessel was built in 1907 and classed with Germanischer Lloyd.

Notation of Lis.8-19, has been assigned.

The Acting Surveyor at Lisbon now reports the vessel has been examined generally in dry dock and found in good order.

The bottom has been cleaned & coated and minor repairs effected.

It is submitted notation of Lis.4-20, be recorded.



© 2021 5. 5. 20

Lloyd's Register Foundation

008434.008438-0119

FR. MAR. 13 1922