

4-SEP 1919

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME _____

Stl. S.S. "LIMA" ex "WESTERWALD". Report

Lis.

No. 1158

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____

When due _____

This vessel was built in 1907 and classed with Germanischer Lloyd.

Notation of "G.L. Lis. 9.18" has been assigned.

The Acting Surveyor at Lisbon now reports the vessel has been examined generally in dry dock and found in good condition.

The bottom has been cleaned & coated, and minor repairs effected.

It is submitted notation -Lis. 8.19* be assigned.

*Lis. 8.19**



© 2021

3. 9. 19

Lloyd's Register Foundation

008434.008438-0127

THE 27 NOV. 1921