

Received from Chief Ship Surveyor..... 27 MAR 1958

SHIP'S NAME "NAGASHIMA MARU" REPORT Yka. No. 2498.
jb

Outstanding Conditions of Class: NONE

Endorsement of Certificate (~~As before~~ or None)

Surveys due:

SPECIAL SURVEY(A) due 2,58.

Signature of Present Survey: (Afloat and in dry dock)

Docking. Special Survey (A).
Wear and tear repairs.
Damage repairs (submerged object).

Special Features:

Interim Certificate in order (Yes-~~No~~ or ~~None~~)

Items Outstanding: (If any for S.S.)

NONE

S.S. ~~to be~~ completed by

Recommendation:

SUBMITTED record of "DS 2,58" and
notation of "SS. Yka. 2,58" be assigned.

S 2,58.
S. Yka. 2,58.

IN L.O.E.
(Main structure partly of P.403 steel) .

IT IS FURTHER SUBMITTED it is concluded the
Surveyors are in error in reporting the anchor chain cable as
being 2.13/16" S.Q. as they were only supplied at 1.7/8"
S.Q., but confirmation is desired.

