

11



PARTS NOW EXAMINED INTERNALLY

AFTER peak

Both port fresh water tanks (under engine room)

Starboard fresh water tank d°

STEERING ENGINE.. Electric motor examined

(Sgd.) S. Fleuret

Surveyor to Lloyd's Register



© 2021

Lloyd's Register  
Foundation

008550-008558-0072