

COPY.

10th September, 1928.

KOBE.

s.s. "TSUKUSHI MARU"

I shall be glad to learn

at arrangements have been made

for carrying out the survey of the

crewshaft which is now due.

State of Tanks when last examined	Being, Six under Smoking Pipe
State of Tanks when last examined	Engine Room Skylights
Water	Oil Pumps (Four in All)
Oil	Engines
Water	Cargo Hatchways
Water	Windows
Water	Fluores
Water	Caulking
Water	Trawl
Water	Brackets
Water	Trussing
Water	Stanchions
Water	Stays
Water	Shrouds



© 2019

Lloyd's Register Foundation

008608-008617-0340