

COPY.

16880

Register of Shipping.

Port of Amsterdam.

2nd of March, 1949.

This is to Certify that


I.G. ten Sijthoff,

the undersigned Surveyor to this Society did at the request of the Representative of the Companhia de Pesca do Centro de Portugal "ARRASTO" of Figueira da Foz, Portugal, attend on board the Motor Trawler "PARGO", in order to state his opinion about the strength of the construction of the stern frame and the landing of the A plates in way of same.

Upon examination it was found that the stern frame lower part had been welded instead of riveted as shown on the approved plan, also that part of the A plate landing to the keel plate in way of the thrust block was found cut away in order to avoid riveting in way.

The welding of the lower part of the stern frame was found good and the landing of the A plate found efficiently strengthened on the inner side and he is of opinion that the construction in way is of equivalent strength compared with the original riveted construction.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Special Damage or Repair Fee (if any) _____

8-4 1949

Received by me,

Recorded in Appendix to Report
to *Figueira*
Voyage _____
Particulars of Classification
as in Register Book
CLASSIFICATION
Special Survey, at Survey and of local Surveys.
41
Continued
board (if assigned to this Ship and now by whom?)
fact
as in
head
lower
by sa
beat
quest
Other Items
Copper, (State When fitted)
Boats
Masts, Yards
Condition (State)
Equipment
Anchor
Cables
" "
Chain
Hawse
Standards
Sails
in the
remain