

COPY.

X
Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

19th March, 1951

Dear Sir,

m.s. "GENERAL SAN MARTIN"

Classn (S)

EJB

With reference to Liverpool First Entry Report No.132467, I shall be glad if you will ascertain from the Surveyors and state the particulars of the breaking tests of the stream wire, hawsers and warps, this information having been omitted from the Report.

With reference to the machinery of this vessel, it is concluded there are three direct bilge suction in Engine room, viz:- 1 at 9", 1 at 6" and 1 at 4" as referred to in the Secretary's letter of 10.6.49, but I shall be glad if you will obtain confirmation from the Surveyors on this point.

The correct MN would appear to be 1581.

Yours faithfully,

Assistant
Clerk to the Classification
Committee.

The Secretary,
LIVERPOOL.



© 2021

Lloyd's Register
Foundation

5800-887800-987200