

# Lloyd's Register of Shipping,

and now verified

3m, 9, 37.

24 JUN 1941 11

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Zuisyo Maru Rpt. Kob No. 11766

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Signature of Surveyor

The Kobe Surveyors report this vessel placed in dry dock, bottom cleaned and coated, ~~repairs to~~ 5 shell plates renewed and minor repairs effected.

// Fracture in sternframe sole piece (ps) after part 17" long x 2" deep repaired by electric welding. The Surveyors recommend this be specially examined at next dry docking.

It is submitted the vessel appears worthy to remain as classed with record of survey 3, 41 as recommended. Subject to the sternframe sole piece EW 3, 41 being specially examined at next dry docking.

100 AI } Subject etc  
3, 41 Kob.)

Insert in GR as recommended



© 2021  
6th

24-6-41  
Lloyd's Register  
Foundation

008796-008503-0007

2, tyome,  
Kozimati-ku.