

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

18 DEC 1951

18 DEC 1951

REPORT ON ANNUAL LOAD LINE SURVEY

Name of Ship "ARGENTINE TRANSPORT" Official Number 169847 Port of Registry LONDONPlace of Survey LIVERPOOL Dates of Survey 3rd & 14th DECEMBER 1951 Date of last Load Line Survey 18/1/51

PARTICULARS OF SURVEY

Items examined.	Condition in which found.	Repairs. Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners	good	reft Renew 37 wood covers, and overhaul end bands.	14/12/51
Beams	good		
Fore and afters	✓		
*Covers ... <u>WOOD & STEEL</u>	good		
*Tarpaulins (2)	good		
(State number per hatchway)	good		
*Cleats and battens	good	✓	
Lashings and their fittings	good		
Wedges	good. Yes.		
(Is supply, including spares, adequate ?)			
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners	✓		
Beams	✓		
Fore and afters	✓		
*Covers	✓		
*Tarpaulins (State number per hatchway)	✓		
*Cleats and battens	✓		
Lashings and their fittings	✓		
Wedges (Is supply, including spares, adequate ?)	✓		
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings	✓		
Beams	✓		
Fore and afters	✓		
Covers	✓		
Tarpaulins (State number per hatchway)	✓		
Cleats and Battens	✓		
Wedges (Is supply, including spares, adequate ?)	✓		
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	good	✓	
Closing arrangements	good		
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	✓		
Closing arrangements	✓		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	good	reft Overhaul hinged flaps, and supply a few wood plugs.	14/12/51
	✓		
7. Within partially enclosed superstructures.			
Closing arrangements	✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddle openings, their covers and fastenings	✓		
Skylights, their fastenings, covers and lashings	good	✓	
	good		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	✓		
11. Within partially enclosed superstructures.			
Doors and fastenings	✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	✓		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	good	reft Overhaul toggles	14/12/51
	✓		

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Ministry of Transport Circular 1687, paragraph 117 (i)).

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle	✓		
Bridge, fore end	✓		
Bridge, after end	✓		
Poop	✓		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	✓		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	Good / <i>except</i> <i>Overhaul valve flap lugs.</i>		14/12/51
17. SIDE SCUTTLES AND DEADLIGHTS	Good /		
18. GUARD RAILS	Good /		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	✓		
20. LIFELINES (fittings and material)	Good /		
21. FREEING PORTS. <i>SLOTS.</i>			
Shutters	Good /		
Protection bars	✓		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	✓		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
24. LOAD LINE MARKS	Good /		
	Verified		3/12/51

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Ministry of Transport Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
ALL	T. B. Tillery	Liverpool	14/12/51

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor T. B. Tillery Place Liverpool Date 14th December, 1951

Signature T. B. Tillery

Date 15th December, 1951.

G.H.W.

21 DEC 1951

Fee £10/-

Number of Visits 2

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.