

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

118 DEC 1956

Pod 11662

40333

REPORT ON ANNUAL LOAD LINE SURVEY

Name of Ship Argentine Transport Official Number 169847 Port of Registry London
 Place of Survey Liverpool Dates of Survey 12/12 and 14/12/56 Date of last Load Line Survey 18th November 1956

PARTICULARS OF SURVEY

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners	Good ✓		
Beams	Good ✓		
Fore and afters	Good ✓		
*Covers	Good except ✓	47 to renew	14/12/56 ✓
*Tarpaulins	Good (3) ✓		
*Cleats and battens	Good ✓		
Lashings and their fittings	Good ✓		
Wedges	Good ✓		
(Is supply, including spares, adequate ?)	Yes ✓		
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners	/		
Beams	/		
Fore and afters	/		
*Covers	/		
*Tarpaulins	/		
(State number per hatchway)	/		
*Cleats and battens	/		
Lashings and their fittings	/		
Wedges	/		
(Is supply, including spares, adequate ?)	/		
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings	/		
Beams	/		
Fore and afters	/		
Covers	/		
Tarpaulins	/		
(State number per hatchway)	/		
Cleats and Battens	/		
Wedges	/		
(Is supply, including spares, adequate ?)	/		
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good ✓		
Closing arrangements	Good except ✓	1 wood plug & 7 canvas covers to supply	14/12/56 ✓
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	/		
Closing arrangements	/		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	Good ✓		
7. Within superstructures not intact or not protected by Class 1 closing appliances.			
Closing arrangements	/		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddly openings, their covers and fastenings	/		
Skylights, their fastenings, covers and lashings	Good except ✓	2 flap hinges to renew	14/12/56 ✓
Deckhouse (Flush Deck Ship)	/		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	Good ✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	/		
11. Within superstructures not intact or not protected by Class 1 closing appliances.			
Doors and fastenings	/		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	/		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good ✓		

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Ministry of Transport Circular 1687, paragraph 117 (i)).



© 2020

Lloyd's Register Foundation

008888-008888-0186

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle ...	/		
Bridge, fore end ...	/		
Bridge, after end ...	/		
Poop ...	/		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures ...	/		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves ...	Good except	2 to re-leather	14/12/56
17. SIDE SCUTTLES AND DEADLIGHTS ...	/		
18. GUARD RAILS ...	Good ✓		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways ...	/		
20. LIFELINES (fittings and material) <i>manila & fittings</i>	Good ✓		
21. FREEING PORTS.			
Shutters ...	/		
Protection bars ...	/		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances ...	/		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
<i>Small hatch to steering flat and to F.P. store</i>	Good except	Steel covers to re-rubber and toggles to overhaul	14/12/56
24. LOAD LINE MARKS ...	Verified in order ✓		

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Ministry of Transport Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined.† († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
all	G. Ord.	Liverpool	14 th December, 1956

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor G. Ord. Place Liverpool Date 14th December, 1956

Signature G. Ord.
Date 15th December, 1956.

Fee £ 17-15-0

Number of Visits (2)

Sub
20.12.56

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.