

Late Name of Vessel (if changed)

WMTG

s. state how many
2 or over

Jan. 5, 19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Wood S. "BLAATIND"

Report Sea

No. 915

For the CHIEF SHIP SURVEYOR ~~CHIEF SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/02.)

Nature of Survey

When due

The Stream & Kedge Anchors require to be replaced by Anchors of correct weight & test

12 A.1 "Salted"

1 Dk. 2 1/2 beams.

A.N.C.P. P 54, F 30.

Subject to a Special Survey equal to a half time Survey at four & eight years, and Subject to Stream & Kedge Anchors being replaced by others of correct weight & test.

29/1/20

It is concluded the sizes of deck & hold beams are as approved. ^{see letter 19/4/20} ~~Out to Surveyors~~ should be requested to state if this is so

Survey Register
Foundation
26-2-20
M. A. S.
H. W.

008953 - 008963 - 0042

We certify that the above is a correct description of the several particulars therein given.

[Signature]

Surveyor's Signature

[Signature: Dis. Cutting & Co. King]