

Received by Chief Ship Surveyor 2.4.18

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steels Sumatra Maru Rpt. Kobe No. 3163

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 49

Depth "d" 16.0

Framing: Table No. 3 page

Description Bulb angle as approved

Longitudinal No. 30415

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.7}{}$

Awwing
Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A.1 (Steel) Awwing DK with freeboard," as recommended. The Summer freeboard of 9' 3 1/2 from centre of disc to top of statutory deck line at Awwing deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 DKs (Steel) & Awwing DK (Steel)

Call DB. 334 11185 F.P.T. 126.E. ART. 935

FK. 6 BH. Cem. Ligature P.



© 2021

Lloyd's Register Foundation