

1

Y. 128

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Std E M/V L.T.C No 3 Report Bos No. 2557**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry When due _____

✠ A.1. (Steel) oil Barge. Carrying Petroleum in Bulk
 " In Service on New York State Barge Canal and from New York
 " to Belfast Inc, via Long Island Sound and Cape Cod Canal
 1 D⁺ (Std) Web Frame, Longitudinal framing, Bracketless System
 F.P.T 125t, A.P.T. 41t
 F.K, 7 B.H, pt asp, Lloyds ACP.
 Q 17', Bridge over machinery space 35'.
 machy aft.

It is concluded the diameter ~~of the~~ ^{the} steering chain is as required but
 the surveyor should be requested to state if this is so

004004-004004-004004

© 2021 Lloyd's Register Foundation
 7/18/30
 31/12/30