

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME INDIA

REPORT Lon.

No. 45267

DBS due 5-60, part held 10-60, now upheld
and completed

Fitted for OF.

New S.V. chests now fitted to both boilers.

It is submitted that this
vessel is eligible to remain
as CLASSED. DBS 6-61

RB notation of OF 6-61

JL.
28-7-61

It is concluded, but surveyor should
confirm, that the air pipes leading from
the oil fuel tanks are fitted with gauge
covers, and that provision has been made
for sounding these tanks.



Lloyd's Register
Foundation