

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stat S.S. FAL SANG*

Report

*J.H.*

No. 17920

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

When due

❖ 100-A-1. (Sld)

2 Dks (Steel &amp; Kaks)

Cell BB 237' 489t, ITa 20' 278t, FPT 52t, APT 46t.

Fk. ABH, Cam, Llyds A.C. P33' B104' Fg8'

*In Ltr 14.12.21*  
 It is concluded a web frame is fitted in the deep tanks as approved but the Surveyors should be requested to state if this is so.