

Received by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME

San Amado

Rpt.

Jrk.

No.

*19905**55-339*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Type of Engine

*Oil Engines 4 S.C.S.A.**8 G. 25 9/16" — 55 1/8"**503 NHP.*

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of approved type

*No main boilers**Yes**No*

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*+ LMC 2.35-**2 DB 180 lb.*

at 11/2/35

ad



© 2020

Lloyd's Register
Foundation

002015-002020-0042

mirrored to retain R & form

© 2020

Lloyd's Register
Foundation



20

108

to direct attention to the better
of the better

at the bottom of the page

1000000000

1000-000000-210000

1000