

2500/12/19

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "ROMAGNE" Report Cleveland. No. 258.

For the CHIEF SHIP SURVEYOR ~~or CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

When due

100 A-1. (steel)

1 Dk. (steel)

Cell DB 204' 476 t.

FPT 38 t.

APT 31 t.

FR. 4 BH. pr. com.

ATC.P

P 27', B 64', F 26'.



© 2020

AEB.

5/11/20

Lloyd's Register
Foundation

height or Outside Brackets above at once
INNER BOTTOM PLATING, breadth and)

WOOD DECK, material & thickness

009630-009039-0217