

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME CARMELITA ex RIO VERDE REPORT Vpo lti No. 18/5/59.

For re-classification, complete surveys of machinery, main and donkey boilers, screwshaft and steam pipes will require to be done.

It is noted that the vessel has been converted to burn oil fuel and from the brief description the system appears to be the "Ray" system which is acceptable. This should be confirmed and if it is not the "Ray" system further particulars should be given. The Surveyor should also ensure that the fittings and controls etc., of oil fuel tanks are to Rule requirements

27/5/59.