

2500, 12, 13.

009074-009082-0206

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Atl. S. S. Baccarat

Report

Cleveland No. 986

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

✱ 100 A1 (Atl.)
1 Bk. (Atl.)

Cecl DB. 204' 515t F.P.T. 38t. APT 81t.

F.K. 4 BH. pt. cem. A.T.O.P. P27' B64' F.26'

S.O. 20/10/20

M. 10B. 2020
8.10.20

The Surveyors should be requested to forward
the water capacity of each of the double bottom tanks, in tons.

no wts 3/11/20

" He
INNER BO

" "

Lloyd's Register
Foundation